Report of Inspection/Test

Annual Special Hazard FM200 System

March 03, 2010

Property Owner/Agent ABC Company **ABC Company** 123 Main Street SW 123 Main Street SW

Anytown, MI 45678

Anytown, MI 45678

Muskegon (231) 726-2396 Grand Rapids (616) 243-6419 Holland (616) 396-6715 Kalamazoo (269) 226-2470 411 Ottawa Street, Muskegon, MI 49442

Conducted by: System Technician

Inspection Ref: 15072

ABC Company Jenny Tutone (616)867-5309 (616)867-5309

Signatures

Inspector - Printed John Pulaski	Inspector - Signature	3/3/10	I state that the information on this form is correct at the time and place of my inspection, and that all equipment tested at this time was left in operational condition upon completion of this inspection except as noted.
Owner - Printed Jenny Tutone	Owner - Signature	3/3/10	Except as noted, the building is occupied with the same occupancy classification and hazard of contents as last inspection. Also, the system has remained in service without modification and been free of actuation of devices or alarms.

Notifications

To Be Notified	Testing	Time	Phone	Contact
ABC Security	Start	2:15 PM	867-5309	George Tyrebyter
Division	End	3:29 PM	867-5309	George Tyrebyter

System and Panel Information

Type FM200	Amount of Agent 25#	Hazard Server Room			
Panel Manufacturer Chemetron	Model Alpha-25	Serial No. 8675309	Location Outside Server Room		
Over current Protection Type	Over current Size (Amps)		Primary Supply Disconnect Location / Panel # / Breaker #		
Breaker	2	20	Telephone Room Panel A Breaker #38		

Cylinder(s)

Equip ID				Cylinder Fill				Inspection - Service									
	Description/	Size	Manufacturer W		Weight		sə	es /el		est	u					d	
Equip ID	Location	Size	Model	Total	Tare	Agent	Gauge Pr	Liquid Lev	Filled	Hydro Te	Condition	Bracket	Gauge	Tagged	Collar Safety Cap	Hose	
	Closet By Server Room	25#	Chemetron Alpha-25	60	35	25	360	7	Ok	Ok	Ok	Ok	Ok	Ok	NA	Ok	Ok

Ok - Passes Inspection S - Serviced on site X - Requires Service NA - Not Applicable

System Function Summary & Test

Function	Description	Test Result
----------	-------------	----------------

Report of Inspection/Test

Annual Special Hazard FM200 System

March 03, 2010

Property: ABC Company **Owner:** ABC Company



Inspection Ref: 15072

System Function Summary & Test

Function	Description	Test
1 direction	Description	Result

Alarm Panel Supervisory Functions							
Panel AC Power Loss	Loss of AC power to the alarm panel is detected by the alarm system.	Pass					
Panel Sec Power Loss	Loss of Secondary power to the alarm panel is detected by the alarm system.	Pass					
Open Alarm Circuits	Electrical opens in initiating and indicating circuits are detected.	Pass					
Short Alarm Circuits	Electrical shorts in initiating and indicating circuits are detected.	Pass					
Panel to Panel Circuits	Integrity of single or multiple circuits providing interface between two or more control panels verified.	Pass					
Ground Faults Detected	Ground faults in alarm and power circuits are detected	Pass					

Alarm Functions - Chemical Suppression							
1st Alarm	A single initiating zone shows alarm.	Pass					
2nd Alarm	A 2nd initiating zone shows alarm.	Pass					
Time Delay	Delay between 1st alarm and agent discharge.	Pass					
Discharge Alarm	Audible alarm upon agent discharge.	Pass					
Agent discharge	Actual discharge of chemical fire suppression agent.	NA					
Abort Switch	Switch prevents discharge of chemical fire suppression agent.	Pass					

Panel Inspection

Yes System was in operation upon arrival?

Yes Panel and surrounding equipment, conduit and wiring well secured and in good condition

Yes Are all lamps and displays operating correctly?

Yes Primary power supply operates properly under full load?
Yes Are drawings and wiring diagrams available at the panel?
Yes Are operating instructions posted or available at the panel?

Yes Are zones labeled and identified?

Chemical Suppression Inspection

Yes Agent control heads or nozzles are in good condition and properly mounted?

Yes All ceiling and floor panels are in place?
Yes Warning signs are proper and visible?

Central Station Test

Digital Type Transmission

Yes Alarm, Trouble and Supervisory indication tested and verified with the central station?

George Tyrebyter Operator spoke to

Alarm Device List

Device Type	Zone/ Address	Location/Description	Manufacturer Model	Physical Condition	ctic Tes
Manual Release Station		Server Room by Door	Notifier NBG-10W	Ok	Ok
Abort Switch		Server Room by Door	Chemetron Abort	Ok	Ok
Horn/Strobe		Server Room Above Door	Gentex GES3	Ok	Ok

Print

Report of Inspection/Test

Annual Special Hazard FM200 System March 03, 2010

Property: ABC Company Owner: ABC Company



Inspection Ref: 15072

Alarm Device List

Device Type	Zone/ Address	Location/Description	Manufacturer Model	Physical Condition	Functional Test
Bell		Server Room Above Door	Gentex GB6-24	Ok	Ok
Smoke Detector		Server Room South	System Sensor 2W-B	Ok	Ok
Smoke Detector		Server Room North	System Sensor 2W-B	Ok	Ok
Horn/Strobe		Outside Server Room	Gentex GES3	Ok	Ok

Alarm Device	Number	7	S	Items serviced	0	0
Summary	of Items	,	X	Items requiring service	0	0